



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
June 3, 2008

Supervisor LK

Mine Name: Travertine 8&9	Permit Number: S0190053
Operator Name: Deloy Shumway	Inspection Date: 05/07/08
Inspector(s): Tom Munson	Time: 1:50-2:30
Other Participants: none	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: As a new inspector to this area, this inspection was mainly to find the site and assess the amount of disturbance.

Inspection Summary: This site does not appear to have been active for sometime. There are scattered piles of rock, some palleted rock and some boulders. The site has several areas on top of the mesa where the travertine is either pushed off the mesa cascading down the slope, picked up at the bottom or excavated from small pits on top of the mesa. There is a small road that is used to access the top of the mesa. It appears to continue past the site and possibly end up by the Green River.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

Thomas Munson

TM:pb

cc: (OPERATOR)

Becky_doolittle@blm.gov

O:\M019-Grand\S0190053-Travertine\inspections\insp-S190053-05072008.doc